

KIWA Japan

Triple H40

Column Traverse Type Horizontal Machining Center




What is QWC ?

The QWC (Quick Work Changer) is Kiwa's unique option for the Triple H40.

Adding a 4th-axis rotary table on a single pallet machine, it performs like a machine with APC. This option also realizes quicker work change compared to the ordinary APC. The machining area and machine front area are divided by slide doors. Workpiece load/unload is possible during cutting (Workpiece on 3 faces can be cut.)

Integration of a robot will help realization of automated mass production solution.

Quick Work Changer



KIWA MACHINERY CO., LTD.